

MBW SERVICE KITS

RAMMER SERVICE KIT #20194

MODELS 420H,421H,422H,440H,442H,480H,482H,483H



MBW RAMMER SERVICE KIT
includes

- FUEL FILTER (01643)
- COVER GASKET (13667)
- FUEL VALVE (16414)
- FUEL VALVE GROMMET (16496)
- SPARK PLUG CR3HSB (0908363777)
- ELEMENT, AIR CLEANER (0172192802)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20194

RAMMER SERVICE KIT #19950

MODELS 480R



MBW RAMMER SERVICE KIT
includes

- FUEL FILTER (01643)
- COVER GASKET (13667)
- FUEL VALVE (16414)
- FUEL VALVE GROMMET (16496)
- SPARK PLUG (0908363777)
- AIR FILTER (0172192802)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 19950

VIBRATORY PLATE SERVICE KIT #20185

AP/GP2000



MBW VIBRATORY PLATE SERVICE KIT
includes

- SHOCK MOUNTS (01011 - 0-0)
- SHOCK MOUNTS (12170 - 0-0)
- V BELT A-30 (01612)
- EXCITER OIL (20186 - 0-02)
- ELEMENT, AIR CLEANER (01721928102)
- SPARK PLUG BPR6ES (09087950840)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20185

TROWEL SERVICE KIT #20181

MODEL F36/4 (GX160)



MBW TROWEL SERVICE KIT
includes

- V BELT (A-27) (01209)
- SPARK PLUG BPR6ES (09087950840)
- ELEMENT, AIR CLEANER (01721928102)
- GEARCASE OIL (01700)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20181

VIBRATORY PLATE SERVICE KIT #20188

AP/GP3550



MBW VIBRATORY PLATE SERVICE KIT
includes

- SHOCK MOUNTS (01011 - 0-0)
- SHOCK MOUNTS (12170 - 0-0)
- V BELT A-31 (00913)
- EXCITER OIL (20186 - 0-02)
- ELEMENT, AIR CLEANER (01721928102)
- SPARK PLUG BPR6ES (09087950840)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20188

TROWEL SERVICE KIT #20183

MODEL F36/4 & F46/4 (GX270)



MBW TROWEL SERVICE KIT
includes

- V BELT (A-29) (01076)
- ELEMENT, AIR CLEANER (01721928115)
- SPARK PLUG BPR6ES (09087950840)
- GEARCASE OIL (01700)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20183

VIBRATORY PLATE SERVICE KIT #20190

GP5800



MBW VIBRATORY PLATE SERVICE KIT
includes

- SHOCK MOUNTS (01011 - 0-0)
- SHOCK MOUNTS (10998 - 0-0)
- V BELT A-37 (00951)
- EXCITER OIL (20186 - 0-02)
- ELEMENT, AIR CLEANER (01721928215)
- SPARK PLUG BPR6ES (09087950840)
- ENGINE OIL (19951 - 1 QT 10W-30)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20190

SCREEDEMON SERVICE KIT #20192

MODEL WS500



MBW SCREEDEMON SERVICE KIT
includes

- O RING (00207)
- BALL BEARING (12614)
- BALL BEARINGS (17608 - 0-0)
- SHOCK MOUNTS (11643 - 0-0)
- RUBBER SEAL (07211)
- FIBER WASHERS (17608 - 0-0)
- ADHESIVE, LOCITEE #426 (10005)

MBW, INC. • 250 Hartford Rd. Slinger WI 53086 USA • mbw@mbw.com Part # 20192

CONTACT MBW TO ORDER YOUR SERVICE KITS!

CALL: 800-678-5237, press option 4

FAX: 262-644-5169

EMAIL: SALES@MBW.COM



WWW.MBW.COM